### **Inspection Report**

Provided by:



#### **Absolute Home Solutions**

Inspector: Terry Gilbert

941-777-2078 terry.gilbert@absolutehomesolutionsfl.com Florida Licensed Inspector #HI11639

### **Property Address:**

123 Sandy Beach Anytown Fl 33333



# Table Of Contents:

Section name:	Section number:
Popert Information	4
Report Information	
Report Summary Page	
Grounds	
Exterior	
Roofing	
Heating - Air	
Electrical	
Plumbing	
Interiors	
Kitchen	
Bath(s)	
Garage - Laundry	
Foundation - Crawl Space	

	1 Report Information
<b><u>Client Information</u></b>	
Client Name	Homer Inspection
<b>Client Phone</b>	941-555-1212
<b>Property Information</b>	
Approximate Year Built	1989
Approximate Square Footage	2000
Number of Bedroom	3
Number of Bath	2
<b>Direction House Faces</b>	South
<b>Inspection Information</b>	
<b>Inspection Date</b>	2-2-2019
<b>Inspection</b> Time	1000 am
Weather Conditions	Overcast
<b>Outside Temperature</b>	72
Price for Inspection	450 - Pre Sale, Wind and 4 Point

Sample Inspection Agreement

### WITHIN THE SCOPE OF THE INSPECTION

The scope of this inspection and report is limited to a visual inspection of the systems and components as listed below, in order to identify those, if any, which may need replacement or repair. See Standards of Practice for a detailed description of the scope of inspection.

#### Exterior:

Landscaping, Retaining Walls, Gutters, Downspouts, Sidewalks and Driveways (both the condition of and as they affect foundation drainage,) Roof, Chimney, Flashing, and Valleys, (for evidence of water penetration and a description of materials,) Siding, Fascia, Soffit, Walls, Widows, Doors, Foundation, Attached Porches/ Decks/ Balconies/ Patios/ Garages (both structural and condition of.)

#### Interior:

Plumbing System: Water Supply/Drains/Vents/Water Heaters/Fixtures, and Locating (But Not Testing) Shut Off Valves; Electrical System: Service Drop, Service Panel, Ground Wire, GFCI Plugs, Switches, Receptacles, Installed Fixtures, and Smoke Detectors; Heating/Cooling System: Permanent Systems, Operating Controls/Filters/Ducts, Insulation, Vapor Barrier, and Ventilation; Bathrooms/Kitchen/Other Rooms: Doors/Windows/Walls/Floors (as to general condition), Cabinets, Counter tops, and Installed Fixtures; Structure: Ceilings/Walls/Floors, Stairs/Basements/Attic/Crawl Spaces (if readily accessible) (as to evidence of water damage and general condition.)

- The scope of the inspection is limited to the description and the general condition of the above systems.

#### OUTSIDE THE SCOPE OF THE INSPECTION

-Any area which is not exposed to view or is inaccessible because of soil, walls, floors, carpets, ceilings, furnishings, lack of access or crawl spaces or any major system (water or electrical systems, heating system, or air conditioner) that is not currently functional is not included in this inspection. -The inspection does not include any destructive testing or dismantling. Client agrees to assume all the risk for all conditions which are concealed from view at the time of the inspection. This is not a home warranty, guarantee, insurance policy, or substitute for real estate disclosures which may be required by law. Whether or not they are concealed, the following are outside the scope of the inspection;

- Building code or zoning ordinance violations - Thermostatic or time clock controls or Low Voltage wiring systems - Geological stability or soils conditions - Water softener or water purifier systems or solar heating systems - Structural stability or engineering analysis - Saunas, steam baths, or fixtures and equipment - Building value appraisal or cost estimates - Pools or spa bodies or sprinkler systems and underground piping - Radio-controlled devices, automatic gates, elevators, lifts, and dumbwaiters - Furnace heat exchanger, freestanding appliances, security alarms or personal property - Specific components noted as being excluded on the individual system inspection form - Adequacy or efficiency of any system or component - Prediction of life expectancy of any item.

- The Inspector is a home inspection generalist and is not acting as an engineer or expert in any craft or trade. If the Inspector recommends consulting other specialized experts, Clients do so at Client's expense.

#### CONFIDENTIAL REPORT

-The written report to be prepared by the Inspector shall be considered the final and exclusive findings of the Inspector/Inspection Company regarding the home inspection at the Inspection Address. The inspection report to be prepared for the Client is solely and exclusively for the Client's own information and may not be relied upon by any other person. Client agrees to maintain the confidentiality of the inspection report and agrees not to disclose any part of it to any other person with the exception of the seller and/or the real estate agents directly involved in this transaction. Client(s) or the inspector may distribute copies of the inspection report to the seller and real estate agents directly involved in this transaction, but neither the seller nor the real estate agent are intended beneficiaries of this Agreement or the inspection report. Client agrees to indemnify, defend, and hold the Inspector/inspection Company harmless from any third party claims arising out of the Client's or Inspectors distribution of the inspection report.

#### DISPUTES

• Client understands and agrees that the Inspector/Inspection Company is not an insurer, that the price paid for the subject inspection and report is based solely on the service provided. Client also agrees that any claim of failure in the accuracy of the report shall be reported to the Inspector/Inspection Company within five business days of discovery and that failure to notify the inspector within that time period shall constitute a waiver of any and all claims. The Inspector/Inspection Company shall have five business days to respond to the claim. If the Inspector/Inspection Company fails to satisfy the claim, liability shall be limited to a refund of the price paid for the Inspection and Report.

Definition of conditions:

AS = Appears Serviceable: The item appeared to be in working or usable condition with no major discrepancies noted.

R = Repair: The item was at or near the end of its useful lifespan. A certified professional should be contacted for further evaluation and repair.

S = Safety Issue: The item is considered a safety hazard and can cause harm to people or property. These items need to be repaired as soon as possible.

NI = Not Inspected: The item was not inspected during the inspection.

# 2 Report Summary Page

This is only a summary of the inspection report and is not a complete list of discrepancies.

1.\*\* The roof looks to have been re covered in the past few years. I was not able to find where a permit was issued for this work in recent years with Pasco County. Inspection from the attic shows that there has possibly been new 5/8 plywood sheeting installed. The ridge gaps vary in size from no gap to 6 inch space between both slopes of roof. I was not able to find any evidence of properly installed valley flashings at any point on the roof.

\*\*Several runs of shingles are crooked indicating non professional installation.

As you enter the home and look to your left you will see a large opening in the roof approximately 5 inches tall by 9 inches wide. This was never enclosed during roof work and you can still see the roof trusses in the attic. This is a potential critter and water intrusion point of entry.

\*\*As you can see from the photos every valley, I was able to lift shingles to expose the runs from opposite slopes. This can allow for water penetration.

2. The kitchen only contains one GFCI outlet. This outlet is not tied in with any other outlets. This is a potential safety hazard and should be evaluated further by a licensed electrician.

3. There is evidence of mold growing on the exterior wall inside the hall bathroom. This may be caused by a potential leak from where the roof valleys meet. Recommend further evaluation by a roofing contractor.

Hall bath GFCI is not in working condition and there are signs of scorching above outlet. Recommend a licensed electrician further evaluates this possible safety issue.

Section	Condition#	Comment
Exterior	5	Common settlement type cracks were observed to the porch. The visible and accessible areas of the porch appeared to be in serviceable condition at the time of the inspection.

### **3** Grounds

### **Grading**

**Grading Slope** 

1) Grading Conditions



The site is slightly sloped.

The soil level was too high at the foundation. We recommend clearing soil away from exterior walls areas, to provide a minimum of 6+ inches between wall coverings and grade. Conditions observed are conducive to wood destroying insect infestation and / or moisture related conditions. At minimum it is recommended that a gutter system be installed to divert water away form foundation.





### Driveways - Sidewalks - Walkways

**Driveway Material** 

Concrete

2) Driveway Conditions



The driveway appeared to be in serviceable condition at the time of the inspection. Common cracks and settlement were observed. The driveway has some surface erosion and minor deterioration.



Absolute Home Solutions

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected

AS



The visible areas of the sidewalk appeared to be in serviceable condition at the time of the inspection. Deterioration and some settlement was observed at the sidewalk.

### **Retaining Wall**

Retaining Wall Material

4) Retaining Wall Conditions



AS

Walls not applicable

## 4 Exterior

### Front - Back Entrance

**Front Entrance Type** 

5) Front Entrance Conditions



Common settlement type cracks were observed to the porch. The visible and accessible areas of the porch appeared to be in serviceable condition at the time of the inspection.





#### **Back Entrance Type**

6) Back Entrance Conditions

**Exterior Walls** 

Structure Type

**Exterior Wall Covering** 

7) Exterior Wall Conditions





Aluminum Sliding Doors nearing end of life. Difficult to slide. Possibly needs track cleaning.Recommend maintenance as needed.

#### Concrete Block

The visible and accessible areas of the exterior siding material are stucco.



No major cracks found in stucco. House has been recently painted in possibly the past 1-2 years best estimate Covered patio post has wood rot. Recommend repair and or maintenance







Patio wood rot on post

# **Exterior Windows - Doors**

Window Type

Single Hung

Aluminum

Window Material

8) Window Conditions



Broken glass pane(s) were observed at 1 window on back of home. Recommend repair as needed. Windows were difficult to open in most cases Recommend maintenance as needed.





Damage Screens on most windows in home





Old Duct tape on window. Possible Mold around window due to possible water leak



Examples of torn and taped screens



### 9) Exterior Door Conditions



Front door right half locking pins damaged. Unable to lock or unlock properly.



Bottom locking mechanism will not lock or unlock properly

#### **Exterior Water Faucet(s)**

**Faucet Location** 

East and West side of home. 2 found

**10) Faucet Conditions** 



The hose faucets appeared to be in serviceable condition at the time of the inspection. Would recommend sealant at wall to prevent moisture intrusion



### **Exterior Electrical**

11) Chimney Conditions



The visible and accessible portions of the chimney(s) appeared to be in serviceable condition at the time of the inspection. Open wires under eave of house on rear corner. Recommend junction box to cover. Recommend maintenance as needed.





Exposed wires on Eave

### **5** Roofing

### **Roof Covering**

**Method of Inspection** 

**Roof Style** 

Roof Covering Material Number of Layers

12) Roof Covering Condition



The roof was inspected by walking the safe and accessible areas.

Hip and Valley

Asphalt composition shingles. 3 tab



Nonprofessional installation. Numerous places where shingle were not fastened or installed properly. Unable to determine if valley flashing was used but could not find any evidence at base of all valleys. Sheeting appears to be newer but ridge caps were not installed correctly. It is suggested that a "Licensed Roofing Contractor" be contacted for further evaluation and repair and or full replacement and evaluation. Drip edge around home was pieced together. Found some as small as 24 inches in length.



Drip edge not overlapped properly



Both Valleys show no sign of being flashed properly







Exposed nail needs sealed. Exposed truss, not flashe properly at gable





Improper installation.





Improper ridge cap install

















Non professional installation



No flashing



Improper installation



Improper Valley install. Picked up shingles.







Improper install





Another valley. Moisture under shingles. possible leak point



Not flashed. Opening to attic and trusses. Leak point

**13) Flashing Conditions** 



The exposed flashings appeared to be in serviceable condition at the

intrusion point

Roof over garage. Critter or moisture



C

time of inspection. Sealing is needed at all vent pipes, chimney, wall and valley seams, and any other through roof projections (including skylights if present) to reduce the possibility of water penetration.





less than 1 inch over lap on drip edge



Improper drip edge



Exposed nail

14) Gutter & Downspout Conditions

Attic Area

Attic Access

**Method of Inspection** 

**Roof Frame Type** 

**15) Attic Conditions** 



No gutters installed

Garage and Hallway

Entered attic area.

The roof framing is constructed with truss framing.



The visible and accessible portions of the attic appeared to be in serviceable condition at the time of the inspection. Limited ventilation. no ridge vents or stacks. Only 2 gable vents





8 inches of blown insulation



Gable vent

**Attic Ventilation Type** 

Attic Ventilation Conditions Attic Insulation Type

16) Attic Insulation Conditions



Loose fill

Gable Vents Soffit vents

The attic has blown-in insulation. The approximate depth of the insulation is  $6 \pm -$  inches. Additional insulation should be considered at some point.

Minimal ventilation was provided to the attic area. This may not be sufficient

to move air through the attic properly. Recommend installing additional vents.

# 6 Heating - Air

### Heating

Location of Unit	Closet off garage
Heating Type	Forced Air
<b>Energy Source</b>	Electric
Approximate BTU Rating	The BTU's were not available.

#### **17) Unit Conditions**



The heating system was operational at time of inspection. This is not an indication of future operation or condition. Air Handler disconnect switch unprofessionally installed. It is suggested that a "Licensed Electrical Contractor" be contacted for further evaluation and repair.





Air Handler disconnect switch. Unprofessional install

#### **Distribution Type**

**18) Distribution Conditions** 

**19) Ventilation Conditions** 

**20)** Thermostat Condition



The visible and accessible portion of the venting flue appeared to be in serviceable condition at the time of the inspection.

The visible and accessible areas of the distribution system appeared to

The visible areas of the heat distribution system is duct-work with registers.

be in serviceable condition at the time of inspection.



The normal operating controls appeared to be serviceable at the time of the inspection.



#### **Air Condition - Cooling**

**Type of Cooling System** Split system **AC Unit Power** 

240V

### **21) AC Unit Conditions**



Outside unit has weeds growing in aluminum vents of compressor. Recommend maintenance as needed.



**Recomend Maintenance on** compressor unit of AC



AC disconnect withing reach of unit

Service Drop - Weatherhea	ad
<b>Electrical Service Type</b>	The electrical service is overhead.

**Electrical Service** Material

**Number of Conductors** 

Aluminum

**22) Electrical Service Conditions** 

1	h	ree	

AS

The main service entry appeared to be in serviceable condition at the time of inspection. Recommend sealing where service wire lines penetrate the exterior wall.

7 Electrical





Electrical roof penetration

# **Main Electrical Panel**

**Main Disconnect** Location

At Main Panel

The main electric panel is located at the garage.

**Electric Panel Location** 

Panel Amperage Rating

**Circuit Protection Type** 

23) Wiring Methods

### 24) Electrical Panel Conditions



Breakers

The main panel appeared to be in serviceable condition at the time of

the inspection. The panel was missing covers where breakers were not installed. Recommend installation of standard plastic covers for safety.

The main power cable is copper. The branch cables are copper.

The electrical capacity of main breaker was listed / labeled as 200 amps.



**Missing Cover** 



### **Electrical Subpanel**

**Subpanel Location** 

25) Subpanel Conditions



No Sub Panels Found during inspection

B. P. P.



### **8** Plumbing

Well System. Breaker or well pump shut off.

### Water Main Line

**Main Shutoff Location** 

Main Line Material

26) Main Line & Valve Conditions

### Water Supply Lines

**Supply Line Material** 

27) Supply Line Conditions

### Drain - Waste Lines

**Drain Line Material** 

28) Drain Line Conditions



The visible portion of the main pipe and valve appeared to be in serviceable condition at the time of the inspection.

The visible material used for the supply lines is copper.

The visible material of the main line / pipe appears to be plastic.



The visible portions of the supply lines appeared to be in serviceable condition at the time of inspection. All of the supply lines were not fully visible or accessible at the time of the inspection.

The visible portions of the waste lines are plastic.



Incorrect drain line installed under kitchen sink. This is a potential point for water leaks from drain in sink.





Wrong downspout from sink.

### Water Heater(s)

#### Water Heater Type

Water Heater Location

Water Heater Capacity

**29) Water Heater Conditions** 



Electric

80 Gallons

Closet off garage

The water heater was operable at the time of inspection. This does not however guarantee future performance, operation, or condition. Age Unknown. Blocked by personal items





30) Septic	Home is on Septic. Not Inspected
31) Well	Pressure appears to be sufficient in home. Not Inspected
	9 Interiors
Walls - Ceilings - Floors	
<b>32) Wall Conditions</b>	AS The general condition of the walls appeared to be in serviceable condition at the time of the inspection. Master Bedroom had holes from knobs swinging
<b>33) Ceiling Conditions</b>	AS The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.
34) Floor Conditions	AS The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.
<b>35) Heat Source</b> <b>Conditions</b>	AS Appears Serviceable
<u>Windows - Doors</u>	
<b>36) Interior Window</b> <b>Conditions</b>	AS Cracked glass pane(s) were observed at. Recommend repair as needed.



### **37) Interior Door Conditions**



The interior doors appeared to be in serviceable condition at the time of the inspection. Several doors in home had minor damage. ie holes and scratches

### **Electrical Conditions**

**38) Electrical Conditions** 





lug in living room no cover and not secured into wall

<b>39) Lighting</b>	Conditions
---------------------	------------

40) Ceiling Fan **Conditions** 



Appears Serviceable



AS

The ceiling fan(s) were operational at the time of the inspection. Mounting hardware of fans, light fixtures, and / or chandeliers was not visible or accessible for inspection.

41) Smoke Detector **Conditions** 



None found Installed

### **Fireplace**

AS = Appears Serviceable	R = Repai	r   <mark>S</mark> = Safety   NI = Not Inspected
Fireplace Location	No fire	place
Fireplace materials		
42) Fireplace Conditions	AS	
		10 Kitchen
Walls - Ceilings - Floors		
43) Wall Conditions	AS	The general condition of the walls appeared to be in serviceable condition at the time of the inspection.
44) Ceiling Conditions	AS	The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.
45) Floor Conditions	AS	The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.
46) Heat Source Conditions	AS	Appears Serviceable
<u> Windows - Doors</u>		
47) Kitchen Window Conditions	AS	The sample of windows tested were operational at the time of the inspection.
48) Kitchen Door Conditions	AS	No doors in kitchen
<b>Electrical Conditions</b>		
49) Electrical	R	No GFCI's installed in kitchen or in breaker panel in garage. It is

**Conditions** 

AS	No doors in
R	No GFCI's i

suggested that a "Licensed Electrical Contractor" be contacted for further evaluation and repair.



Kitchen outlet pulled out of wall

**50) Lighting Conditions** 



Appears Serviceable

AS

AS

51) Ceiling Fan
-----------------

**Conditions** 

Not Inspected

### Kitchen Sink - Counter tops - Cabinets

- 52) Counter Conditions
- Formica Counters. .Minor wear was observed at the counters.
- **53) Cabinet Conditions**

AS

Several Cabinet door hinges are loose. Recommend tightening for safety

54) Sink Plumbing Conditions

R	





55) Garbage Disposal Condition	AS			
Appliances				
Stove - Range Type	The oven is electric. The range is electric.			
56) Stove - Range Condition	AS The oven was in operational condition at the time of the inspection. This does not however guarantee future conditions after the time of inspection. Appears Serviceable			
57) Hood Fan Conditions	AS The fan / hood and light were in operational condition at the time of the inspection.			
58) Dishwasher Conditions	AS Not Inspected			
11 Bath(s)				
Walls - Ceilings - Floors				
59) Wall Conditions	AS Hall Bath found evidence of Mold possibly from roof. Recommend maintenance as needed.			





Mold evidence. Ceiling has been recently painted

**60) Ceiling Conditions** 

<b>61) Floor Conditions</b>
-----------------------------

62) Heat Source **Conditions** 

#### Windows - Doors

**63) Bathroom Window Conditions** 

64) Bathroom Door **Conditions** 

**Electrical Conditions** 

**65) Electrical Conditions** 

$\left[ \right]$	AS	
_		_

AS

AS

The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection. The ceilings appeared to be freshly painted. This condition may hide, mask, or conceal previous conditions not visible at the time of this inspection.



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.



**Appears Serviceable** 



Some of the window screens were ripped and / or torn.



The interior doors appeared to be in serviceable condition at the time of the inspection. The doors stick at the door-frame at. Repairs and / or adjustments are recommended.



GFCI in hall bath does not work. Scorching above outlet. It is suggested that a "Licensed Electrical Contractor" be contacted for further evaluation and repair.



### **66) Lighting Conditions**

AS	Appears Serviceable
----	---------------------

AS

67) Vent Fan Conditions

**Bathroom Sink** 

68) Counter - Cabinet Conditions



Appears Serviceable



69) Sink Conditions

### **Shower - Tub - Toilet**

70) Shower - Tub Conditions



The sink appeared to be in serviceable condition at the time of inspection in bath



Shower/bathtub water faucet falls off Recommend maintenance as needed.





Handle Falls off

**71) Toilet Conditions** 



The toilet appeared to be in serviceable condition at the time of inspection in bath

# 12 Garage - Laundry

### Walls - Ceilings - Floors

**Garage Type** 

72) Wall Conditions

73) Ceiling Conditions



Block walls. The general condition of the walls appeared to be in serviceable condition at the time of the inspection.





Hole in ceiling. Possibly from previous water damage



74) Floor Conditions



AS

The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

**75) Window Conditions** 

No windows

#### 76) Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.

77) Vehicle Door Conditions



Seals around door worn. Recommend maintenance as needed. The vehicle door(s) appeared to be in serviceable condition at the time of the inspection.



Seals around door worn

78) Electrical Conditions

**79) Lighting Conditions** 

Appears Serviceable

Appears Serviceable

### Laundry Room

Location

Off kitchen

AS

AS

80) Laundry Room Conditions



The visible and accessible portions of the laundry plumbing components appeared to be in serviceable condition at the time of inspection.



# **13 Foundation - Crawl Space**



## **Foundation**

Foundation Type	Slab on grade
Foundation Material	Concrete
81) Foundation Conditions	AS Appear serviceable at time of inspection. Minor wear on floor.